




ANTIGRAVITY MITER JIG




Note: Make 2 Clamping Blocks. On one block, mount the clamp parallel to the length. On the other, mount it perpendicular.


Clamping Block



Top View



Top View



Edge View
Sliding Table